1	2	3	4	5
October, 93	180	—	65	33
November, 93	84	—	129	—
December, 93	105	—	81	—
January, 94	110	—	129	3
February, 94	85	—	130	109
March, 94	3	—	177	113
1994-95				
April, 94	40	—	96	222
May, 94	50	—	99	197
June, 94	43	—	90	160
July, 94	73	—	74	155
August, 94	100	—	24	190
September, 94	123	—	10	144
October, 94	97	—	76	152
November, 94	67	—	129	98

SOURCE : Quick Reports of Coal India Limited.

Designed Quality of Coal in Dankuni

1748. SHRI DIPANKAR MUKHERJEE:

SHRI M. A. BABY :

Will Ihe Minister of COAL be pleased to refer to the answer to Unstarred Question No. 3490 given in the Rajya Sabha on 22nd August, 1994 and state:

(a) whether the designed quality of the coal was available;

(b) if so, whether it has been proposed to bring low phosphorous coal by transport from Talcher and Chirirairi collieries in the new action plan;

(c) whether it is a fact that ECL is supplying ROM Coal with 40% slack at the rate of IR to 29 rakes a month which is not sufficient for operation of two retort benches at full capacity;

(d) whether this quaVtty of coal is as per the original design envisaeed for this coal complex and if so, details thereof; and if not, reasons therefor;

(el what is the justification that insufficient gas supply by Calcutta Gas Supply i» the main problem in maximisation oi production in view of the report of General Manager, Dankuni Coal Complex that 1 and 2 retort benches require major maintenance and repair; and

(f) whether quality of tar from the complex is as per the designed norm and if not, the reasons therefor ?

THE MINISTER OF STATE IN THE MINISTRY OF COAL (SHRI P. A. SANGMA): (a), (c) and (dl Deigned quality of coal from Raniganj Coal mines having coni handling facilities is generally being received; However, at times, coal with more fine is received whenever supplies are from mines without proper coal handling facilities.

(b) Yes, Sir.

(e) The main reason for low utilisation of the plant is due to the failure of the linked consumer, Greater Calcutta Gas Supply Corporation (GCGSC) to draw the agreed volume of gas from the plant. Some of the retorts required clearing of the clinker formation at the bottom portion which was resulting in drop in productivity. Some of the retorts have already been cleaned out and put back into the nomal operation and other retorts ara under the process of cleaning of clinkers.

(f) The tar produced has slightly lower specific gravity than the design and the likely reason for variation in specific gravity is due to lower temperature operation than th; design profile.

Supply of coal to Tamil Nadu Electricity Board

1749. SHRI RAMACHANDRAN PILLAI:

SHRI NILOTPAL BASU:

Will the Minister of COAL be pleased to state :

(a) what are the details of coal linkage and actual sunply of coal bv Coal India Limited to Tamil Nadu Electricity Board (TNEB) during the last three years;

(b) what has been the average shortfall at linkage allocation of coal to Tamil Nadu Llrctricity Board during the above period;

(ri what is the anticirtated shortfall in supply of coal to Tamil Nadn F>ctricity Board so far in the current year 1994-95 ; and